





# Workshop on "Radiological characterisation for decommissioning", Studsvik, Sweden 17-19 April 2012

Cristina Correa, Esther García Tapias, José Luis Leganés ENRESA, (Spain)



1. Introduction. PIMIC Decommissioning Project Overview and Lenteja incident.

enresa


- 2. Initial radiological characterisation.
- 3. Execution works and Radiological criteria
- 4. In situ radiological characterisation.
- 5. Final radiological survey.
- 6. Conclusions.



## Introduction: Decommissioning of Research Facilities at CIEMAT

## CIEMAT Spanish Centre for Energy related, Environmental and Technological Research

- \* Research Reactor
- Pilot Reprocessing
   Plant
- Conditioning and Storage Plant for Liquid Waste
- \* ENRESA started
   Dismantling works in
   2006 and were finished
   in 2010.
- \* Soil Restoration Activities (2010-2012)
  - \* "Lenteja"





about 25 Ci (9,2E+11 Bq) Cs-137
 about 30 Ci (1,1E+12 Bq) Sr-90


(enresa

#### Introduction: Leakage incident.

- Soil was contaminated as a result of a pipe leakage, in the 70's
- At that time, part of the soil was removed, filled the holes with clean soil and covered with a concrete slab.
- Some activity remained in the ground.
- In 2010 Enresa started the execution of remediation activities.
- On March 2012 the excavated zone has been refilled




enresa



## terization and Remediation at CIEMAT



## Initial radiological characterization



- Three different boreholing surveys were performed (S7, S8, S9; 2004 - 2006).
- Nº of samples: 277
- Main Radionuclides: Sr-90 & Cs-137, Alpha traces
- Range: From "0" up to 10<sup>4</sup> Bq.g-1 of Cs-137 & Sr-90
- Soil Volume estimate: 3,000 m3
- The affected area estimated was of 450 m2 & up to 8 m deep.

- 5 m deep: significantly decreased
- 9 m: less than 1 Bq/g




#### Initial radiological characterization: Distribution of contaminants

## Statistical Analysis of Sr90/Cs137 values

Two different groups of samples are Sr90/Cs137≈ 300 clearly identified Two different isotopic zones were MUELLE DE CARCA RANEA , I ∎ defined: Sr90/Cs137≈1 1191 Sr/Cs = 1 (FCL) S8-20 ENTRADA/SALIDA 14 **DE CARRETILLAS** Sr/Cs = 300 (PAL)14 811 ÁREA DE PREDOMINIO DEL ESPE POZO A LENTE S8-28 S7.S94.S98 Sr-90 S96.S91.S92.S8 S95,S97 PAL and an and a second 0000400 200000 4000400 8.000400 8.000400 (20040) 니그 ARQUETA A ATAR. Cs-137 FCL TANQUES 🛱 N EXTERIORES Ē to ATARJEA 01.01.07 FCL PAL ISOTOPE % TOTAL % TOTAL ZONA ARQUETA 'B' DE PASO Y CAMBIO Pu-238 0.1150% 0.00079 0.3730% 0.0023% Pu-239 Pu-241 2.2900% 0.0140% E DELIMITACIÓN DE ISOT Sr-90 44.3000% 99.7000% ENTRADA/SALIDA REC/ NTO HERMÉTICO RECINTO NO HERMÉTICO U-234 0.1290% 0.0008% 220 m2 U-235 0.0122% 0.0001% 8 Sr90/Cs137≈1 U-236 0.0079% 0.0000% U-238 0.0496% 0.0003% Am-241 0.1920% 0.0012% 52.5000% 0.3190% Cs-137

## (enresə

## Initial radiological characterization: Distribution of contaminants



9



## **Execution Works**

(enresa



- Objectives of remedial actions :
  - To segregate contaminated soil and no contaminated soil in order to release the clean soil coming from the excavation.
  - The soil and subsurface, after the soil removal activities, have to meet the radiological requirements and then to fill the excavated area with clean material.

enresa



## **Radiological criteria**


- Material Clearance levels: European Commission Recommendations
   RP122 (soil removed)
- Building rubble, Structure and building Surfaces Clearance
   levels: EC Recommendations RP 113
- Soil: release levels (top 15 cm).
  - 100 µSv/year Industrial Worker Scenario
  - 1 mSv/year Resident Farmer Scenario (if Institutional Control Fails)
  - CALCULATION: RESRAD v6.4
- Subsurface Soil: no residual activity at depth

	Material Clearance	Soil Release
Sr-90	1 Bq/g	0,62 Bq/g
Cs-137	1 Bq/g	0,86 Bq/g

## **Execution Works: preparatory works**

- Structures demolition
- Underground pile wall (50 m perimeter, 15 m deep = 425 m<sup>3</sup>) to content the excavation area





enresa

## Soil Radiological





8:0

The Bobcat





## **Execution works: Preparatory works**





## **Execution works**




## 450 m<sup>2</sup>

(enresə



## **Execution works**





## **Execution works: Final Situation**



9,20 m

# In-situ radiological characterization and material segregation

enresa



In-situ radiological characterization and material segregation

## **OBJECTIVE:**

- To segregate material free release, VLLW and LILW
- To assign isotopic composition (scaling factors) to each waste container (\*)


(\*) Sample of each container (metallic box, Textile-Bag)








## In-situ radiological characterization and material segregation





## In-situ radiological characterization and material segregation



(enresa

In-situ radiological characterization and material segregation

## MATERIAL CLEARANCE

## **Clearance Process**

Based on "Box-Counter", a four germanium detector for Gamma spectrometry.





Disposal at El Cabril

VLLW &LILW are transported to Spanish disposal center of El Cabril



(enresa

In-situ radiological characterization and material segregation

## **Excavation completed:**

- 66 % Released Material:
  - 1,878 tons
- 34 % Radioactive waste
  - VLLW (961 tons)
    LILW (7 tons)







(enresa

## Final radiological survey



Objective: to demonstrate that radiological criteria are met:

(enresa

- Walls (surface clearance levels RP113)
- Soil:
  - top 15 cm (release levels)
  - At depth (no residual activity)




## Final radiological survey

- <u>Wall surface</u>: MARSSIM methodology (Nureg 1575)
  - Scan surface (1 x 1 m<sup>2</sup>) using scintillation counters (beta counter for surface contamination)
  - Static measurements: 13 locations for each survey unit (2)



## Final radiological survey

- Soil and subsurface:
- 1. Checking the top 15 cm (MARSSIM methodology)
  - Scan surface (1 x 1 m<sup>2</sup>) by using scintillation counters (beta counter)
  - Scan surface by using INa detector (100 % coverage)
  - Static measurements:15
     locations Sodium iodide
     detector (top15 cm)



enresa



## Final radiological survey



## 2. Depth Checking:

- 15 borehole at 2 m deep in the static measures locations
- 6 judgmental borehole at6 and 8 m deep.
- 3 samples were
   obtained from each
   borehole

Final radiological survey

Final radiological survey results:

- 1. Soil and subsurface:
  - The top 15 cm: below release levels
  - No residual activity at depth.
- 2. Walls: residual activity below clearance levels for reuse.
- 3. Walls were insulated using a system of shotcrete.




enresa

4. Lenteja excavation was release from radiological requirements and the filling was performed as conventional work.







31



## Final radiological survey





## Conclusions

Three radiological characterization processes:

1.Initial radiological characterization:

- Scope of work (surface and depth, volume of soil)
- Management of materials (isotopic composition/scaling factors, radwaste, material clearance)
- 2.In-situ radiological characterization:
  - Segregation of material (soil removed) for release and rad-waste.
- 3. Final radiological survey:
  - Verification that the resulting excavation and subsurface fulfill the regulatory requirements.

Previously the filling, the radiological final report was submitted to the Spanish Regulatory Authority



